

Practical Boat Repair (grin)

After working many weeks restoring a 1968 Coronado 34 in San Carlos, my son and his buddies were feeling very proud, still lots of work to do but a great start. One chore was to grind out the glassed in chain plates and replace them. With the dust flying inside there was a mishap and two 4 inch slots were cut into their recently painted hull. No worries, my son came up with the perfect solution, something you might consider in similar circumstances.



Free Spirit after many weeks of work



The Hull after many weeks and a bad 5 minutes



Free Spirit after a few weeks of work

THE SOLUTION

